



Accessories

Accesorios

Accessoires

Acessórios

ZSG

ZSG 40

ZSG 67


ZSG 120

ZSG 160

ZSG 225

ZSG 400

ZSG 600



ZSG kw	Star-Delta starter Motor rating	Arranque estrecha delta Datos motor	Dé marreur é toile triangle Puissance moteur	Arranque estrela triangular Potência do motor
X	Starter casing	Carenado arranque	Boitier contacteur	Invólucro do arranque
Y	Assembly plate	Montaje de obturación	Montage d'obturation	Placa de montagem
Z	Foot	Pie	Socle	Pé

ZSG	Complete part assembly no.	kw	[inches]			Part no.		
			a	b	c	X	Y	Z
40	206400	4-5.5	9.84	7.40	5.91	820611	-	521094
67	206401	5.5-7.5	9.84	7.40	5.91	820611	-	521094
120	206402	7.5-12.5	9.84	7.40	5.91	820612	-	521094
160	206403	12.5-18.5	9.84	7.40	5.91	820613	522806	521094
225	206404	18.5-30	14.76	9.84	5.91	820614	522806	521094
400	206405	30-37	14.76	14.76	5.91	820615	522807	521094
600	206406	37-55	14.76	14.76	5.91	820716	522807	521094

Depending on the supply characteristics we would recommend a star/delta starter for a motor of more than 4 kw. For rotary vane vacuum pumps and compressors we would additionally recommend an unloading valve.

De acuerdo con las características de suministro, recomendaríamos un arranque tipo estrecha-delta para un motor de más de 4 kw. Para las bombas y compresores de vacío de paletas rotativas, recomendaríamos además una válvula de descarga.

Nous préconisons un démarreur é toile triangle pour toute motorisation supérieure à 4 kw, si toutefois le réseau le permet. Pour les pompes à vide et compresseurs à palettes ceci implique une décharge au démarrage.

Dependendo das características fornecidas, recomendamos um arranque estrela triangular para um motor de capacidade superior a 4 kw. No caso das bombas a vácuo e compressores de palheta rotativa, recomendamos ainda uma válvula de descarga.

ZA 910

3.7.93

Rietschle Inc.

7222 Parkway Drive

Hanover, MD 21076 USA

☎ 410-712-4100

Fax 410-712-4148

E-Mail:

info@rietschlepumps.com

http://

www.rietschlepumps.com